MISSOURI DEPARTMENT OF HEALTH
STATE PUBLIC HEALTH LABORATORY

DATAMASTER MAINTENANCE REPORT

BREATH ALCOHOL PROGRAM
JUN -8 2
DHSS STATE HEALTH LAB.

Complete this report in duplicate at the time of the regular monthly preventive maintenance check, and whenever instrument is repaired. Send copy to Department of Health; retain original in department file.

DATAMASTER SN	DATE OF INSPECTION
201235	06-01-2009
LOCATION OF INSTRUMENT (STREET AND CITY)	TIME OF INSPECTION
1501 South Duquesne Road, Joplin, Mo, 64801	23:08

CHECKLIST: Place a check (✓) to the left of each item if found to be satisfactory or if operating within established limits. (Write in observed values where determined.) Unchecked items must be corrected before using instrument.

- ☑ DIAGNOSTIC CHECK (PRINTOUT ATTACHED)
  - ☑ COMPUTER
  - ☑ DETECTOR
  - ☑ PROGRAM
  - ☑ FILTERS
  - ☑ HEATERS SAMPLE CHAMBER 48 °C
  - ☑ QUARTZ STANDARD
  - ☑ FLOW DETECTOR
  - ☑ CALIBRATION
  - ☑ PUMP HIGH SPEED
  - ☑ PRINTER
- ☑ INDICATOR LIGHTS
- ☑ TIME AND DATE
- ☑ SIMULATOR TEMPERATURE (34 °C ± 0.2°C) 34.0
- ☑ CALIBRATION CHECK - passed

  Run three tests using a standard solution. All three tests must be within ± 5% of the standard value and must have a spread of .005 or less. Check the box corresponding to the standard solution being used. (PRINTOUT ATTACHED) (USE RECIRCULATION PUMP)

  ☑ 0.100% STANDARD - MUST READ BETWEEN 0.095% and 0.105% INCLUSIVE

  ☐ ~~0.040% STANDARD - MUST READ BETWEEN 0.038% and 0.042% INCLUSIVE~~

  (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)

TEST 1	TEST 2	TEST 3
.100	.100	.100

- ☑ PERFORM R.F.I. TEST (PRINTOUT ATTACHED) passed
- ☑ NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF BREATH TESTS IN EACH RANGE AS FOLLOWS: **(DO NOT INCLUDE SIMULATOR TESTS)**

REFUSALS	(0-.04)	(.05-.09)	(.10-.14)	(.15-.19)	(Over .19)
4	6	2	2	0	0

List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily and within established limits (use other side if necessary)

Instrument meets D.O.H.S.S. specifications Software chip replacement

RepCo Lot #08002 Expiration Date: 10-13-2010 .10 Vapor

INSPECTING OFFICER

SIGNATURE	PRINT NAME
▶	Joseph Houdyshell
TYPE II PERMIT NUMBER/EXPIRATION DATE	TELEPHONE NUMBER
820346 / 01-07-2011	(417) 781-4823

AN EQUAL OPPORTUNITY/AFFIRMATIVE ACTION EMPLOYER
services provided on a nondiscriminatory basis

REPCO MARKETING INC.

3101-156 STONYBROOK DRIVE
RALEIGH, N.C. 27604
919-878-5460

CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc.
LOT NUMBER: 08002
EXPIRATION DATE: October 13, 2010 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number 08002 of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed utilizing a gas chromatograph and found to contain 0.1209 gms/dl wt/vol ethyl alcohol in aqueous solution (i.e. ethanol).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of 0.100% +/-3% when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator.

The date of manufacture for this lot number is October 14, 2008. The expiration date for this lot number is October 13, 2010 at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President
RepCo Marking, Inc.

Form MO 01

FACE THIS SIDE DOWN - THIS EDGE IN FIRST

BAC DataMaster
Evidence Ticket

STATE OF MISSOURI
DUQUESNE POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 201235
06/01/09
23:11

--- DIAGNOSTIC CHECK ---

COMPUTER:	OKAY
PROGRAM (04-07-2009):	OKAY
HEATERS	
SAMPLE CHAMBER:	48c
FLOW DETECTOR:	OKAY
PUMP	
HIGH SPEED:	OKAY
DETECTOR:	OKAY
FILTERS:	OKAY
QUARTZ STANDARD:	OKAY
CALIBRATION:	OKAY

PRINTER TEST
!"#$%&'()*+,-./0123456789:;<=>?@ABCDEFG
HIJKLMNOPQRSTUVWXYZ[\]^_`abcdefghijklmno
pqrstuvwxyz{|}~

RATOR SIGNATURE

Stock No.
1

REORDER ALL SUPPLIES FROM N.P.A.S.
P.O. BOX 1435, MANSFIELD, OH 44901

FACE THIS SIDE DOWN - THIS EDGE IN FIRST

BAC DataMaster
Evidence Ticket

STATE OF MISSOURI
DUQUESNE POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 201235
06/01/09

ARREST TIME: 21:00
SUBJECT NAME:
RFITEST
DOB: 01/01/70 SEX: M
STATE/D.L.: MO/123456789
ARRESTING OFFICER:
HOUDYSHELL/JOSEPH
OFFICER I.D.: 803
TESTING OFFICER:
HOUDYSHELL/JOSEPH
OFFICER I.D.: 803
PERMIT NUMBER: 820346
EXPIRATION DATE: 01/07/11
MISCELLANEOUS DATA:
RFITEST
NA

--- BREATH ANALYSIS ---

BLANK TEST	.000	23:15
INTERNAL STANDARD	VERIFIED	23:16
RADIO INTERFERENCE		

OPERATOR SIGNATURE

Card Stock No.
60021

REORDER ALL SUPPLIES FROM N.P.A.S.
P.O. BOX 1435, MANSFIELD, OH 44901

FACE THIS SIDE DOWN - THIS EDGE IN FIRST

BAC DataMaster

Evidence Ticket

STATE OF MISSOURI
DUQUESNE POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 201235
06/01/09

TESTING OFFICER:
HOUDYSHELL/JOSEPH/L
OFFICER I.D.: 803
PERMIT NUMBER: 820346
EXPIRATION DATE: 01/07/11
MISCELLANEOUS DATA:
NA
NA

--- SUPERVISOR MODE ---

BLANK TEST	.000	23:08
INTERNAL STANDARD	VERIFIED	23:08
EXTERNAL STANDARD	.100	23:08
BLANK TEST	.000	23:09
EXTERNAL STANDARD	.100	23:09
BLANK TEST	.000	23:10
EXTERNAL STANDARD	.100	23:10
BLANK TEST	.000	23:11

N = 3
SIM. = .1
AVG. = .1

OPERATOR SIGNATURE

Card Stock No.
60021

REORDER ALL SUPPLIES FROM N.P.A.S.
P.O. BOX 1435, MANSFIELD, OH 44901

State of Missouri
DEPARTMENT OF HEALTH

PERMIT
TYPE II

JOSEPH HOUDYSHELL

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

DATAMASTER

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

Date 01/07/09

Number 820346

Expires 01/07/11

John J Mathewson

Director of State Public Health Laboratory

Director, Department of Health

MO 580-0771 (7-88)

Lab. 4 (R7-88)