MISSOURI DEPARTMENT OF HEALTH
STATE PUBLIC HEALTH LABORATORY
DATAMASTER MAINTENANCE REPORT

BREATH ALCOHOL PROGRAM

Complete this report in duplicate at the time of the regular monthly preventive maintenance check, and whenever instrument is repaired. Send copy to Department of Health; retain original in department file.

DATAMASTER SN: 940097

DATE OF INSPECTION: 6/1/09

TIME OF INSPECTION:

LOCATION OF INSTRUMENT (STREET AND CITY): 324 S Miller Sweet Springs Mo

CHECKLIST: Place a check (✓) to the left of each item if found to be satisfactory or if operating within established limits. (Write in observed values where determined.) Unchecked items must be corrected before using instrument.

- [✓] DIAGNOSTIC CHECK (PRINTOUT ATTACHED)
  - [✓] COMPUTER
  - [✓] DETECTOR
  - [✓] PROGRAM
  - [✓] FILTERS
  - [✓] HEATERS SAMPLE CHAMBER 49 C
  - [✓] QUARTZ STANDARD
  - [✓] FLOW DETECTOR
  - [✓] CALIBRATION
  - [✓] PUMP HIGH SPEED
  - [✓] PRINTER
- [✓] INDICATOR LIGHTS
- [✓] TIME AND DATE 14:31 6/1/09
- [✓] SIMULATOR TEMPERATURE (34 °C ± 0.2 °C) 34°C ± 0.2°C
- [✓] CALIBRATION CHECK -

  Run three tests using a standard solution. All three tests must be within ± 5% of the standard value and must have a spread of .005 or less. Check the box corresponding to the standard solution being used. (PRINTOUT ATTACHED) (USE RECIRCULATION PUMP)

  - [✓] 0.100% STANDARD - MUST READ BETWEEN 0.095% and 0.105% INCLUSIVE
  - [ ] 0.040% STANDARD - MUST READ BETWEEN 0.038% and 0.042% INCLUSIVE

  (ONLY ONE STANDARD IS TO BE USED PER MAINTENANCE REPORT)

TEST 1	TEST 2	TEST 3
.096%	.096%	.096%

- [✓] PERFORM R.F.I. TEST (PRINTOUT ATTACHED)
- [✓] NUMBER OF REFUSALS, SINCE LAST MAINTENANCE REPORT, AND NUMBER OF BREATH TESTS IN EACH RANGE AS FOLLOWS: **(DO NOT INCLUDE SIMULATOR TESTS)**

REFUSALS	(0-.04)	(.05-.09)	(.10-.14)	(.15-.19)	(Over .19)
0	0	0	0	0	1

List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily and within established limits (use other side if necessary)

This instrument is operating within Dept of Health specifications using .100% solution from RepCo Mktg bearing lot # 0800 manufacture date Feb 12 2008 and expiration date Aug 11 2009.

INSPECTING OFFICER

SIGNATURE: Melvin Taber

PRINT NAME: Melvin Taber

TYPE II PERMIT NUMBER EXPIRATION DATE: 820 272 09/18/10

TELEPHONE NUMBER: 660 335 6823

REPCO MARKETING INC.

3101-188 STONYBROOK DRIVE
RALEIGH, NC 27604
919-876-5480

CERTIFICATE OF ANALYSIS

MANUFACTURER AND SUPPLIER: RepCo Marketing, Inc.
LOT NUMBER: 08001
EXPIRATION DATE: August 11, 2009 at 11:59 p.m.

RepCo Marketing, Inc. certifies the following:

RepCo Marketing, Inc. manufactured, tested and supplied Lot Number **08001** of Alcohol Certified Solution for simulators. Random samples of said lot number were analyzed utilizing a gas chromatograph and found to contain **0.1216** gms/dl wt/vol ethyl alcohol in aqueous solution (i.e. ethanol).

The alcohol and distilled water used in the solution were found to be free of any interfering substance.

This solution will produce a vapor alcohol value of 0.100% +/-3% when heated to 34 Degrees Celsius +/-0.2 Degrees Celsius in a simulator.

The date of manufacture for this lot number is **February 12, 2008.** The expiration date for this lot number is **August 11, 2009** at 11:59 p.m.

This document is a true representation of the original Certificate of Analysis.

Cecil B. Garner, President
RepCo Marketing, Inc.

FACE THIS SIDE DOWN - THIS EDGE IN FIR

BAC DataMaster
Evidence Ticket

STATE OF MISSOURI
SWEET SPRINGS POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 940097
06/01/09

TESTING OFFICER:
TABER/MELLVIN/L
OFFICER I.D.: 902
PERMIT NUMBER: 820272
EXPIRATION DATE: 09/18/10
MISCELLANEOUS DATA:
MONTHLY MAINTENANCE TEST
SUPERVISOR TEST

--- SUPERVISOR MODE ---

BLANK TEST	.000	14:41
INTERNAL STANDARD	VERIFIED	14:41
EXTERNAL STANDARD	.096	14:42
BLANK TEST	.000	14:42
EXTERNAL STANDARD	.096	14:43
BLANK TEST	.000	14:43
EXTERNAL STANDARD	.096	14:44
BLANK TEST	.000	14:44

N = 3
SIM. = .1
AVG. = .096
S.D. = 0
S.E. = -4

OPERATOR SIGNATURE Melvin Taber

CARD STK # 60036

REORDER ALL SUPPLIES FROM N.P.A.S.
P.O. BOX 1435, MANSFIELD, OH 44901

FACE THIS SIDE DOWN - THIS EDGE IN FIRST

BAC DataMaster
Evidence Ticket

STATE OF MISSOURI
SWEET SPRINGS POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 940097
06/01/09

ARREST TIME: 14:15
SUBJECT NAME:
NO/BODY
DOB: 01/23/53 SEX: M
STATE/D.L.: MO/123456789
ARRESTING OFFICER:
TABER/M/L
OFFICER I.D.: 902
TESTING OFFICER:
TABER/M/L
OFFICER I.D.: 902
PERMIT NUMBER: 820272
EXPIRATION DATE: 09/18/10
MISCELLANEOUS DATA:
MONTHLY MAINTENANCE TEST
RADIO INTERFERENCE TEST

--- BREATH ANALYSIS ---

BLANK TEST	.000	14:49
INTERNAL STANDARD	VERIFIED	14:49
RADIO INTERFERENCE		

OPERATOR SIGNATURE Melvin Taber

CARD STK # 60036

REORDER ALL SUPPLIES FROM N.P.A.S.
P.O. BOX 1435, MANSFIELD, OH 44901

FACE THIS SIDE DOWN - THIS EDGE IN FIRST

BAC DataMaster
Evidence Ticket

STATE OF MISSOURI
SWEET SPRINGS POLICE DEPARTMENT

BAC DATAMASTER SERIAL NUMBER 940097
06/01/99
14:21

---- DIAGNOSTIC CHECK ----

COMPUTER:	OKAY
PROGRAM:	OKAY
HEATERS SAMPLE CHAMBER:	49c
FLOW DETECTOR:	OKAY
PUMP HIGH SPEED:	OKAY
DETECTOR:	OKAY
FILTERS:	OKAY
QUARTZ STANDARD:	OKAY
CALIBRATION:	OKAY

PRINTER TEST
!"#$%&'()*+,-./0123456789:;<=>?@ABCDEFG
HIJKLMNOPQRSTUVWXYZ[\]^_`abcdefghijklmno
pqrstuvwxyz{|}~+

OPERATOR SIGNATURE

CARD STK #
60036

REORDER ALL SUPPLIES FROM N.P.A.S.
P.O. BOX 1435, MANSFIELD, OH 44901

State of Missouri
DEPARTMENT OF HEALTH

PERMIT
TYPE II

MELVIN L. TABER

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field repairs, and operate the following breath analyzer(s):

DATAMASTER

for the determination of the alcoholic content of blood from a sample of expired (alveolar) air. Issued under the provisions of sections 577.020 through 577.041, RSMo 1986.

Date 09/18/08

Number **820272**

Expires 09/18/2010

Director of State Public Health Laboratory

Director, Department of Health

MO 580-0771 (7-88)

Lab. 4 (R7-88)